



**PRODUCT EVALUATION REPORT OF CMWS EQUIPMENT UNDER IRMNCH & NUTRITION PORGRAM PUNJAB DURING FY 2018-19**

<b>Irem No.</b>	<b>Name of Items/Participated Firms</b>	<b>Brand Name</b>	<b>Make/Country of Origin</b>	<b>(Approved/ Not)</b>	<b>Remarks</b>
<b>1</b>	<b>Delivery Table</b>				
	M/s New Era Technologies	Local	Pakistan	Approved	(As per Specifications)
	M/s Orient Medicals	Local	Pakistan	Approved	(As per Specifications)
	M/s Thankful Agencies	Local	Pakistan	Approved	(As per Specifications)
	M/S Total Technologies Private Limited	Local	Pakistan	Approved	(As per Specifications)
	M/s Noorani Surgical	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (Rusted, Instable, Improper Finish at the joints. Poor quality (Not upto the mark).
	M/s Medi Source	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (Rusted, Instable, Improper Finish at the joints. Poor quality (Not upto the mark).
	M/s Paradise Export	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (Rusted, Instable, Improper Finish at the joints. Poor quality (Not upto the mark).
	M/s Qazzafi Surgical	Local	Pakistan	Approved	
	M/s Conqueror Surgical Private Limited		Pakistan		Sample Not Submitted
	M/s Strongman Medical Products		Pakistan		Sample Not Submitted
	M/s Real Tech Scientific Intl.		Pakistan		Sample Not Submitted
<b>2</b>	<b>CLINICAL STOOL (STEEL)</b>				
	M/s New Era Technologies	Local	Pakistan	Approved	(As per Specifications)
	M/s Orient Medicals	Local	Pakistan	Approved	(As per Specifications)
	M/s Thankful Agencies	Local	Pakistan	Approved	(As per Specifications)
	M/s Mirza Niaz Muhammad & Sons	Local	Pakistan	Approved	(As per Specifications)
	M/s Noorani Surgical	Local	Pakistan	Approved	(As per Specifications)
	M/s Medi Source	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (The legs are not welded with the Central Dia as per given specifications, Improper Finishing).
	M/s Paradise Export	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (Sample is not finished and very poor quality). Not upto the mark
	M/s Qazzafi Surgical	Local	Pakistan	Approved	(As per Specifications)
	M/s Quintex Medical	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (The sample is instable and not properly finished).
	M/s Strongman Medical Products	Local	Pakistan		Sample Not Submitted
	M/s Impact International	Local	Pakistan		Sample Not Submitted
	M/s Life Tech	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (Sample is Rusted, Instable and Improper Finishing). Poor quality. Not up to the mark.
	M/s Maaven Healthcare	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (The sample has Magnetic Top instead of Stainless Steel and improper finishing).
<b>3</b>	<b>STEEL ALIMIRAH</b>				
	M/s Orient Medical	Local	Pakistan	Approved	(As per Specifications)
	M/s Thankful Agencies	Local	Pakistan		Sample Not Submitted
	M/s Mirza Niaz Muhammad & Sons	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (The color of the sample and inner spacing is not proper, Flaws in joints, Rusted, Poor quality glass (not fixed properly), Safety Hazards, Poor quality locks, breakable.
	M/s Noorani Surgical	Local	Pakistan		Sample Not Submitted
	M/s Medi Source	Local	Pakistan		Sample Not Submitted
	M/s Qazzafi Surgical	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (Broken glass, Thefttable locks, Improper Finishing, Safety Hazards and Rusted. Not up to the mark.
	M/s Strongman Medical Products	Local	Pakistan		Sample Not Submitted
<b>4</b>	<b>MEDICINE CABINET (TROLLEY)</b>				
	M/s Orient Medical	Local	Pakistan	Approved	(As per Specifications)
	M/s Thankful Agencies	Local	Pakistan		Sample Not Submitted
	M/s Noorani Surgical	Local	Pakistan	Approved	(As per Specifications)

	M/s Medi Source	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (Inner spacing, Multicolor and Rusted).
	M/s Qazzafi Surgical	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (Shelf glass given, easily breakable).
	M/s Quintex Medicals	Local	Pakistan	Sample Not Submitted	
	M/s Strongman Medical Products	Local	Pakistan	Sample Not Submitted	
	M/s Maaven Healthcare	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. (The glass is not frosted, spacing issue and rusted).
	M/s Conqueror Surgical Private Limited	Local	Pakistan	Sample Not Submitted	
5	<b>(NORMAL DELIVERY) INSTRUMENT KIT FOR CMW</b>				
	M/s Orient Medical	falcon brand	Falcon sialkot	Approved	(As per Specifications)
	M/s Thankful Agencies			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
	M/s Noorani Surgical			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
	M/s Medi Source			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
	M/s Qazzafi Surgical			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
	M/s Quintex Medicals			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
	M/s Paradise Export			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
	M/s Maaven Healthcare			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
	M/s Life Tech			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
	M/s Surgiquips	Hilbro	Hilbro Sialkot	Approved	(As per Specifications)
	M/s Medap International			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
	M/s Professional Hospital Furnishers			Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found poor coating contact alignment in most of the instruments. The joints mechanism is not smooth and have rough surface.
6	<b>B,P APPARTUS (USA/Japan/EU)</b>				
	M/s Metro Commercial Enterprises	RIESTER	RIESTER GERMANY	Approved	(As per Specifications)
	M/s Orient Medical	FOCAL CO	FOCAL CO JAPAN	Approved	(As per Specifications)
	M/s Star Tech International	FGC	FGC JAPAN	Not Approved	M/s Qazzafi Surgical has also quoted the same company which is not possible. Fukugawa is not manufacturer. Further, the company has no sale certificate issued by the manufacturer.
	M/s Noorani Surgical	YAMASU	YAMASU JAPAN	Not Approved	Authority letter to sale the products submitted on company's letter head. No model number of the brand quoted..
	M/s Medi Source	ALPK2	ALPK2 JAPAN	Not Approved	Fukugawa is not manufacturer. Further, no supply order for the quoted product is attached with the bid to assess the experience of the quoted product in the marker.
	M/s Qazzafi Surgical	FGC	FGC JAPAN	Not Approved	M/s Star Tech International has also quoted the same company which is not possible. Fukugawa is not manufacturer. Further, the company has no sale certificate issued by the manufacturer.
	M/s Quintex Medicals	FAZZINI	FAZZINI ITALY	Not Approved	Sample is very poor and not as per specifications mentioned in the bidding documents.

	M/s Hi MOD Technologies	ROSSMAX	ROSSMAX SWITZERLAND		Sample Not Submitted
	M/s BMITCO Business	CERTEZA	CERTEZA GERMANY		Sample Not Submitted
<b>7</b>	<b>WEIGHING MACHINE ADULT</b>				
	M/s Vital Care				Sample Not Submitted
	M/s Total Technologies Pvt Limited	Shekel H150-7	France/ROC	Approved	(As per Specifications)
	M/s BMITCO Business				Sample Not Submitted
	M/s Surgiquips	Buerer PS-240	Germany	Approved	(As per Specifications)
	M/s Medi Source	Detecto	USA	Not Approved	The firm has not attached any of the supply order of the quoted item to assess the market availability of the product.
	M/s Qazzafi Surgical	Rossmax WB-101	Switzerland	Approved	(As per Specifications)
	M/s Quintex Medicals	Momert/5253	Hungry	Not Approved	The firm has not attached any of the supply order of the quoted item to assess the market availability of the product.
<b>8</b>	<b>BABY WEIGHING MACHINE</b>				
	M/s Vital Care				Sample Not Submitted
	M/s Total Technologies Pvt Limited	Shekel H650-1	France/ROC	Approved	(As per Specifications)
	M/s BMITCO Business				Sample Not Submitted
	M/s Surgiquips	Beurer BY-80	Germany	Not Approved	The top of the weighing scale is not detachable as per the specifications. Further, the firm has not attached any of the supply order of the quoted item to assess the market availability of the product.
	M/s Medi Source	SECA 354	Germany	Not Approved	The firm has not attached any of the supply order of the quoted item to assess the market availability of the product.
	M/s Star Tech International	LAICA BF 2051	Italy	Approved	(As per Specifications)
	M/s Quintex Medicals	Memort ZRT 6475	Hungry	Approved	(As per Specifications)
<b>9</b>	<b>AMBU BAG (BABY)</b>				
	M/s Quintex Medicals	Fazzini srl 0722C 1+ 0701+0729	Italy	Approved	(As per Specifications)
	M/s Vital Care				Sample Not Submitted
	M/s BMITCO Business				Sample Not Submitted
	M/s Star Tech International	Hum System/ HBB05-B-01R	Germany	Not Approved	The firm has neither any of the supply order of the quoted item to assess the market availability of the product nor the product as per specifications.
	M/s Bestech Enterprises				Sample Not Submitted
	M/s Apex Enterprises				Sample Not Submitted
<b>10</b>	<b>CMW KIT BAG</b>				
	M/s Quintex Medicals	Local	Pakistan	Approved	(As per Specifications)
	M/s Medi Source	Local	Pakistan	Not Approved	The submitted sample is of poor quality.
<b>11</b>	<b>FETOSCOPE</b>				
	M/s Orient Medical	Local	Pakistan	Approved	(As per Specifications)
	M/s Human Health Care	Local	Pakistan		Sample Not Submitted
	M/s Noorani Surgical	Local	Pakistan	Approved	(As per Specifications)
	M/s Surgiquips	Local	Pakistan	Approved	(As per Specifications)
	M/s Qazzafi Surgical	Local	Pakistan	Approved	(As per Specifications)
	M/s Quintex Medicals	Local	Pakistan	Approved	(As per Specifications)
<b>12</b>	<b>MEASURING TAPE</b>				
	M/s Quintex Medicals	Local	Pakistan	Approved	(As per Specifications)
	M/s Bestech Enterprises		China	Not Approved	The measuring tape is not 1 inches wide as per specifications. Low quality.
<b>13</b>	<b>STETHOSCOPE</b>				
	M/s Metro Commercial Enterprises	RIESTER	GERMANY	Approved	(As per Specifications)
	M/s Orient Medical	FOCAL CO	JAPAN	Approved	(As per Specifications)
	M/s Star Tech International	ADC	USA	Not Approved	The firm has not attached any of the supply order of the quoted item to assess the market availability of the product.
	M/s Noorani Surgical	YAMASU	JAPAN	Not Approved	The firm has not attached any of the supply order of the quoted item to assess the market availability of the product.
	M/s Medi Source	ALPK2	JAPAN	Not Approved	The firm has not attached any of the supply order of the quoted item to assess the market availability of the product.
	M/s Qazzafi Surgical	ROSMAX	SWITZERLAND	Not Approved	The firm has not attached any of the supply order of the quoted item to assess the market availability of the product.
	M/s Quintex Medicals	FAZZINI	ITALY	Approved	(As per Specifications)
	M/s Life Tech	ERKA	GERMANY		Sample Not Submitted
	M/s BMITCO Business	CERTEZA	GERMANY		Sample Not Submitted
	M/s Vital Care	SPLINGER	SPLINGER FRANCE		Sample Not Submitted
<b>14</b>	<b>STERILIZER</b>				
	M/s Medap International	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found Rusted with a poor quality cable. Further, no supply order attached for the quoted product.
	M/s Orient Medical	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found with a poor quality cable.

	M/s Thankful Agencies	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found Rusted with a poor quality cable.
	M/s Mirza Niaz Muhammad & Sons	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found Rusted with a poor quality cable.
	M/s Noorani Surgical	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found Rusted without cable.
	M/s Medi Source	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample found Rusted with a poor quality cable.
	M/s Paradise Export	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the cable was found of very poor quality.
	M/s Qazzafi Surgical	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the cable was found of very poor quality.
	M/s Quintex Medicals	Local	Pakistan	Approved	(As per Specifications)
	M/s Surgiquips	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the cable was of very poor quality and found broken.
	M/S Bestech Enterprises	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample was found Rusted with incomplete accessories. Further, the firm has no supply orders for the quoted product.
	M/s Maaven Healthcare	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the cable was found of very poor quality. Further, the firm has no supply orders for the quoted product.
<b>15</b>	<b>SYRINGE CUTTER</b>				
	M/s Noorani Surgical	Local	Pakistan	Approved	(As per Specifications)
	M/s Orient Medical	Local	Pakistan	Approved	(As per Specifications)
	M/s Qazzafi Surgical	Local	Pakistan	Approved	(As per Specifications)
	M/s Quintex Medicals	Local	Pakistan	Approved	(As per Specifications)
	M/S Bestech Enterprises	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample was found of very poor quality. Further, the firm has no supply orders for the quoted product.
	M/s Total Technologies Pvt Limited	Local	Pakistan	Not Approved	The sample was of plastic body which is not as per specifications.
	M/s Medi Source	Local	Pakistan	Not Approved	The Committee physically inspected the samples in respect of Material Workmanship and Stability. Following are the shortcomings in the submitted sample. During evaluation, the sample was found of very poor quality. Further, the firm has no supply orders for the quoted product.
<b>16</b>	<b>SAFETY BOX</b>				
	M/s Qazzafi Surgical	Local	Pakistan	Approved	(As per Specifications)
	M/s Total Technologies Pvt Limited	Local	Pakistan	Approved	(As per Specifications)
	M/s Human Health Care	Local	Pakistan	Not Approved	The sample was of very poor quality.
	M/S Bestech Enterprises	Local	Pakistan		Sample Not Submitted
<b>17</b>	<b>CMW SIGN BOARD</b>				
	M/s Qazzafi Surgical	Local	Pakistan	Approved	(As per Specifications)
	M/s Quintex Medicals	Local	Pakistan		Sample Not Submitted
	M/s Medi Source	Local	Pakistan		Sample Not Submitted